

McMILLAN PAZDAN SMITH

FIELD REPORT

WCI GROUP LLC

FIELD REPORT

PROJECT: Leavelle McCampbell Middle

FIELD REPORT NO.: Forty-Seven (47)

CONTRACT: Construction Management @ Risk
HG Reynolds

ARCHITECTS
PROJECT NO.:



First floor electrical rough in is ongoing as framing scope is aggressive



View of standing rain water as site has received (4") in the last to evenings.
Manageable, as framing scope continues.


FIELD REPORT

PROJECT: Leavelle McCampbell Middle

FIELD REPORT NO.: Forty-Seven (47)

CONTRACT: Construction Management @ Risk
HG Reynolds

ARCHITECTS
PROJECT NO.:



First floor HVAC duct supply, fire alarm security installation continues



See framing in administration offices, as well as fire alarm system rough install, with supply ducts

McMILLAN PAZDAN SMITH

WCI GROUP LLC

FIELD REPORT

PROJECT: Leavelle McCampbell Middle

FIELD REPORT NO.: Forty-Seven (47)

CONTRACT:

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Forty-Seven (47)

CONTRACT: Construction Management @ Risk **ARCHITECTS**
HG Reynolds **PROJECT NO.:**
