

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Twenty (21)

CONTRACT: Construction Management @ risk **ARCHITECTS**
HG Reynolds **PROJECT NO.:**

1) CSRA inspecting CMU before grouting.

DEFICEINT WORK: N/A

PHOTOS: Attached



Laying up of CMU wall Area A

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Twenty (21)

CONTRACT: Construction Management @ risk **ARCHITECTS**
HG Reynolds **PROJECT NO.:**

FIELD REPORT

PROJECT: Leavelle McCampbell Middle

FIELD REPORT NO.: Twenty (21)


CONTRACT: Construction Management @ risk
HG Reynolds

ARCHITECTS
PROJECT NO.:

FIELD REPORT

PROJECT: Leavelle McCampbell Middle **FIELD REPORT NO.:** Twenty (21)

CONTRACT: Construction Mem.04 r2gement @ r1 **ARCHITECTS**
HG Rey r2lds **PROJECT NO.:**



Prm.04ep for placement of concreteRebar

