



FIELD REPORT

---

PROJECT: Leavelle McCampbell Middle FIELD REPORT NO.: Twenty Four (25)

CONTRACT: Construction Management @ risk ARCHITECTS  
HG Reynolds PROJECT NO.:

---

DEFICEINT WORK:

- 1) Installation of inlet protection
- 2) [REDACTED]ilt fence @ boxes

FIELD REPORT

---

<u>PROJECT:</u>	Leavelle McCampbell Middle	<u>FIELD REPORT NO.:</u>	Twenty Four (25)
<u>CONTRACT:</u>	Construction Management @ risk HG Reynolds	<u>ARCHITECTS</u> <u>PROJECT NO.:</u>	

---



Improperly Maintained silt fences @ boxes

FIELD REPORT

---

PROJECT: Leavelle McCampbell Middle FIELD REPORT NO.: Twenty Four (25)

CONTRACT: Construction Management @ risk ARCH 0 0e W\* n BT /F2  
HG Reynolds


FIELD REPORT

---

PROJECT: Leavelle McCampbell Middle FIELD REPORT NO.: Twenty Four (25)

CONTRACT: Construction Management @ risk ARCHITECTS  
PROJECT NO.:

---



Topping off Gym wall

FIELD REPORT

---

PROJECT: Leavelle McCampbell Middle FIELD REPORT NO.: Twenty Four (25)

CONTRACT: Construction Management @ risk ARCHITECTS  
HG Reynolds PROJECT NO.:

---


FIELD REPORT

---

PROJECT: Leavelle McCampbell Middle FIELD REPORT NO.: Twenty Four (25)

CONTRACT: Construction Management @ risk ARCHITECTS  
HG Reynolds PROJECT NO.:

---



Erecting - building scaffolding @ Gym Wall






FIELD REPORT

---

PROJECT: Leavelle McCampbell Middle FIELD REPORT NO.: Twenty Four (25)

CONTRACT: Construction Management @ risk ARCHITECTS  
HG Reynolds PROJECT NO.:

---



Prep for concrete placement piers @ canopy








FIELD REPORT

---

PROJECT: Leavelle McCampbell Middle FIELD REPORT NO.: Twenty Four (25)

CONTRACT: Construction Management @ risk ARCHITECTS  
PROJECT NO.:

---



Erosion and Improperly maintained silt fence

Report by: Bill Williams