



FIELD REPORT

---

**PROJECT:** Leavelle McCampbell Middle **FIELD REPORT NO.:** Thirty One (31)

**CONTRACT:** Construction Management @ risk **ARCHITECTS**  
HG Reynolds **PROJECT NO.:**

---


**INSPECTIONS:**

1) CSRA tested welding of steel and bolt connections.

**DEFICEINT WORK:**

Correction to CSRA Steele Report No. T-16-U63

**PHOTOS:** Attached



Joist - Area D

**FIELD REPORT**

---

**PROJECT:** Leavelle McCampbell Middle

FIELD REPORT

---

**PROJECT:** Leavelle McCampbell Middle

FIELD REPORT

---

**PROJECT:** Leavelle McCampbell Middle **FIELD REPORT NO.:** Thirty One (31)

**CONTRACT:** Construction Management @ risk **ARCHITECTS**  
HG Reynolds **PROJECT NO.:**

---

Prep of

FIELD REPORT

---

**PROJECT:** Leavelle McCampbell Middle

**FIELD REPORT NO.:** Thirty One (31)

**CONTRACT:** Construction Management @ risk  
HG Reynolds

**ARCHITECTS**  
**PROJECT NO.:**

---



Damper beneath flashing Area D

**McMILLAN PAZDAN SMITH**